

November 17th, 2015

City of Greensboro P.O. Box 3136 Greensboro, N. C. 27401 Attn: Mr. Kenny Carroll

Re: City of Greensboro Contract 2015-5194

Change Order #2 (Revised) Request by City of Greensboro

The following is a revised summary of the costs necessary for the Change Order #2 request to existing utilities as requested by the City of Greensboro:

Storm Drain:

Oversize Curb Inlet on 54"	\$2,500.00	
Undercut Excavation along		
& 54" Storm (Haul of	\$8.246.00	
Select Backfill for Undercu	t	
#57 Stone	220.48 tons @ \$27	\$5,952.96
ABC Stone	90.87 tons @ \$24	\$2,180.88
Core holes in Pipe		\$800.00
Cut/Relay Sanitary Sewer	\$1,500.00	
Added Oversize Drop man	\$2,800.00	
Added Oversize manhole at Sta. 2+45		\$2,500.00
Remove/Replace Existing 2	24" Storm with RCP	
at Sta. 1+15		\$1,440.00

Total Storm Drain: \$27,919.84

(See Page 2 of 2)

Lindsey Street Waterline:

Pour deadman on existing 10" waterline	\$1,700.00
Cap 10" water main-variable range coupling	\$600.00
Cap 10" water main-10" DI	\$60.00
Cap 10" water main-10" Cap	\$200.00
Cap 10" water main-cut/remove pipe	\$300.00
Revise tie-in location-12" DI	\$800.00
Revise tie-in location-asphalt repair	\$369.00

Total Lindsey Street Waterline: \$4,029.00

Administration Costs (15%) \$4,792.33

Total Change Order #2 Request: \$36,741.17

The attached revised breakdown for the Change Order, as requested by the City, is provided by Yates Construction Company. Please review the information and let us know of any questions or additional information needed.

The information should be in line with the items discussed and reviewed in your meeting with Mr. John Boelhower. We would request this be reviewed and processed in a timely manner.

STORM DRAIN UPGRADES

20 Undercut excavation in Eugene St. and on Lindsay St. for 8" water and 54" RCP (see attached quantity breakdown). Undercut (waste off-site)
St. for 8" water and 54" RCP (see attached quantity breakdown). Undercut (waste off-site) 3) Select backfill for undercut 57 Stone 220.48 TN 27.00 \$5,952.96 ABC Stone 90.87 TN 24.00 \$2,180.88 FOOTAL STORM DRAIN UPGRADES Core Holes in Pipe 2 EA 400.00 \$800.00 \$1,500.00 \$1,500.00 \$2,3
S7 Stone ABC Stone 90.87 TN 24.00 \$2,180.88 No. 24.00 \$2,180.80 No. 24.00 \$2,180.00 No. 24.00 \$2,180.00 No. 24.000 \$2,300.00 No. 24.000 \$2,300.00 No. 24.000 \$2,300.00 No. 24.000 \$2,2800.00 No. 24.000 No.
S7 Stone ABC Stone 90.87 TN 24.00 \$2,180.88 No. 24.00 \$2,180.80 No. 24.00 \$2,180.00 No. 24.00 \$2,180.00 No. 24.000 \$2,300.00 No. 24.000 \$2,300.00 No. 24.000 \$2,300.00 No. 24.000 \$2,2800.00 No. 24.000 No.
ABC Stone 99.87 TN 24.00 \$2,180.88 \$8,133.84 \$1,000 \$2,180.88 \$1,000 \$2,180.88 \$1,000 \$2,180.88 \$1,000 \$2,180.88 \$1,000 \$2,180.88 \$1,000 \$2,180.88 \$1,000 \$1,500.00 \$1,500.00 \$1,500.00 \$2,300.00 \$2,300.00 \$2,300.00 \$2,300.00 \$2,300.00 \$2,300.00 \$2,300.00 \$2,300.00 \$2,500
Total Select Backfill \$8,133.84
Core Holes in Pipe 2 EA 400.00 \$800.00
Core Holes in Pipe 2 EA 400.00 \$800.00 \$1,500.00 \$1,500.00 \$2,300.00 \$2,300.00 \$2,300.00 \$2,300.00 \$2,300.00 \$2,800.00 \$2,800.00 \$2,800.00 \$2,800.00 \$2,500.00 \$2,
Cut/Re-Lay Sanitary Service 1 LS 1500.00 \$1,500.00 \$2,300.00 5) Added oversize drop manhole at 2+00 1 LS 2800.00 \$2,800.00 6) Added oversize manhole at 2+45 1 LS 2500.00 \$2,500.00 7) Remove and replace existing 24" clay w/RCP at 1 LS 1440.00 \$1,440.00 \$1,440.00 1+15 LT (This is to bring invert up to get over the Duke Power duct bank in Lindsay) TOTAL STORM DRAIN UPGRADES \$27,919.84
\$2,300.00 5) Added oversize drop manhole at 2+00 1 LS 2800.00 \$2,800.00 6) Added oversize manhole at 2+45 1 LS 2500.00 \$2,500.00 7) Remove and replace existing 24" clay w/RCP at 1 LS 1440.00 \$1,440.00 1+15 LT (This is to bring invert up to get over the Duke Power duct bank in Lindsay) TOTAL STORM DRAIN UPGRADES \$27,919.84
5) Added oversize drop manhole at 2+00 1 LS 2800.00 \$2,800.00 6) Added oversize manhole at 2+45 1 LS 2500.00 \$2,500.00 7) Remove and replace existing 24" clay w/RCP at 1 LS 1440.00 \$1,440.00 Duke Power duct bank in Lindsay) TOTAL STORM DRAIN UPGRADES \$27,919.84
6) Added oversize manhole at 2+45 1 LS 2500.00 \$2,500.00 7) Remove and replace existing 24" clay w/RCP at 1 LS 1440.00 \$1,440.00 1+15 LT (This is to bring invert up to get over the Duke Power duct bank in Lindsay) TOTAL STORM DRAIN UPGRADES \$27,919.84
7) Remove and replace existing 24" clay w/RCP at 1 LS 1440.00 \$1,440.00 1+15 LT (This is to bring invert up to get over the Duke Power duct bank in Lindsay) TOTAL STORM DRAIN UPGRADES \$27,919.84
1+15 LT (This is to bring invert up to get over the Duke Power duct bank in Lindsay) TOTAL STORM DRAIN UPGRADES \$27,919.84
LINDSAY STREET WATER UPGRADES
LINDSAY STREET WATER UPGRADES
ADDITIONAL WORK
-Pour deadmen on existing 10" water main: 2 EA 850.00 \$1,700.00
Tour dedurment on containing the victor manner of the the victor manne
- Cap 10" water main
Variable Range Coupling 1 EA 600.00 \$600.00
10" DI 3 LF 20.00 \$60.00
10" CAP 1 EA 200.00 \$200.00
Cut/Remove Pipe 1 LS 300.00 \$300.00
Total to Cap 10" Warer Main \$1,160.00

⁻ Revise tie-in location

- Revise tie-in location

TOTAL WATER UP	GRADES			\$4,029.00
Total to Revise Tie-In Location				\$1,169.00
Asphalt Repair	3	SY	123.00	\$369.00
12" DI	10	LF	80.00	\$800.00